XK3190-D10

WEIGHING INDICATOR

MANUAL

PLEASE READ THIS MANUAL VERY CAREFULLY BEFORE USE

CONTENTS

- 1. GETTING STARTED
- 2. TECHNICAL PARAMETERS AND SPECIFICATIONS
- 3. LAYOUT AT FRONT AND BACK
- 4. Connecting to Other Devices
- 5. Calibration and password setting
- 6. Operation
- 7. Save and print
- 8. CODE DISPLAY

APPENDIX

1. GETTING STARTED

CAUTION

- This is not a toy. Keep out of reach of children;
- This indicator is not an explosion proof device;
- This indicator is not a water proof device;
- Do not open this indicator, no user serviceable parts inside.
 Always contact supplier for service.

1.1 Introduction

Weighing indicator XK3190-D10 adopts high precision Σ - Δ A/D conversion technology, widely applied in electronic floor scale, electronic truck scale, static railroad truck scale and so on alike static weighing system equipped with 1~8 load cell.

1.2 Features

- Good consistency, no need to re-calibrate a scale if change the former indicator, just input the recorded former calibration parameter is OK
- Software on-line update and modification locally or by ISP
- Printing content and format user-defined
- Aluminum alloy housing with strong anti-disturbance ability, ESD method for printer and communication interface
- Password settable for operation of parameter setting, record check, record clear;
- Password revisable for time power off function

- Able to save data in operation mode of one time weighing or two times weighing, with selection of print or not;
- Able to save 100 customer records, one record consists of customer ID, customer name, note info;
- Able to save 201 goods records, one record consists of goods ID, goods name;
- Able to save 1500 truck records, one record consists of truck ID, truck tare weight, and weighing data able to print out all weighing records or weighing records that accord to user's requirement, or weighing records that group by date, truck ID, goods ID, customer ID
- Able to save 1501 weighing records
- Standard RS232 communication interface with selectable baud rate and communication method
- Standard scoreboard interface with current loop method
- Standard parallel print interface, able to connect with 9-pin or 24-pin wide-line printer
- With built-in printer for D10P

2.TECHNICAL PARAMETERS AND SPECIFICATIONS

- Model:XK3190-D10
- Accuracy: Class III, N=5000
- A/D Conversion Method: $\Sigma \Delta$
- Input Signal Range: -15mV ~ 30mV
- A/D conversion speed: 200 times/sec.
- Nonlinearity: $\leq 0.0015\%$ FS
- Load Cell Excitation: DC5V; I:120mA
- Max. connection number of load cell: 8 at 350 ohm or 16

at 700 ohm

- Load cell connection mode: 6 wire, auto compensation for long distance
- Max. sensitivity: 0.5uV/d
- Display: 7 bits LED, 7 status indications, 3 battery indications
- Clock: real clock without effect on power off
- Scoreboard interface (Standard)

Serial sending signal by current loop with baud rate 600. Transmission distance: Current loop≤2000 meters;

• Communication interface (RS232 C standard; RS422 optional)

Serial communication interface, with selectable baud rate by continuous sending method or on command method

Transmission distance: RS232C≤30 meters; RS422≤1200 meters


Print interface (Standard)

Parallel sending, able to connect with wide-line printer KX-P1121 \ KX-P1131 \ LQ300K;


- Power supply: AC 187~242V,49~51HZ;DC:6V/10Ah
- Fuse:0.5A

3. LAYOUT AT FRONT AND BACK

3.1 Front view of the indicator




3.2 Back view of the indicator



4. Connecting to Other Devices 1 through various interfaces

4.1 Connection to load cell

Connect this indicator to load cell through the 9-pin load cell connector located at the back. Refer to the below table for load cell pin assignment.



PIN #	ASSIGNMENT
1	E-
2	S-
5	SHIELD
6	E+
7	S+
8	IN-
9	IN+

Short connect PIN 1 AND PIN 2, PIN 6 and PIN 7 when connected to load cell with a 4-wire cable;

CAUTION

• Connection between load cell and indicator must be reliable; shield-wire must be connected to ground reliably;

¹ Turn scale off and cut off power before making any connections or disconnections.


-

• Load cell and indicator are all static-electricity-sensitive devices, measures must be taken to ensure safety.

4.2 Connection to PC or SCOREBOARD

From the 15-pin interface located at the back, you could

- Connect indicator to computer via RS232 output or RS422 output (optional);
- Connect indictor to scoreboard via 20mA current loop output;



15-pin connector

PIN #	ASSIGNMENT	PIN #	ASSIGNMENT
1	RS422 OUTPUT+	9	SCOREBOARD OUT+
2	RS422 OUTPUT-	10	SCOREBOARD OUT-
3	RS422 IN+		
4	RS422 IN-		
6	RS232 RXD		
7	RS232 TXD		
8	GND		

Note1: RS422 output is optional;

4.2.1 Connect to PC

Data format for RS232 or RS422 is the same. Data is transmitted in ASCII code. Data format is as listed below(one group):

1	2	3	4	5	6	7	8	9	10
START				DA	.TA				STOP

There are two modes to communicate with PC:

- Continuously send, and (when TF set as 0)
- Command mode (when TF set as 1)

A. Continuously send

Data transmitted is tare weight from the display of the indicator. Each time it sends one frame data to pc, one frame consists of 12 groups while the data format of one group is as listed above. Below is the content for one frame:

GROUP	CONTENT	NOTES		ΕΣ	KAMPLE
NO.		CONTENT	CODE	CONTENT	CODE (HEX)
1	START	(XON)	02	XON	02
2	+ or -	SIGN BIT	2B/2D	+	2B
3		Highest		0	30
4				0	30
5	WEIGHING		30~39	2	32
6	DATA		30 - 3 9	0	30
7	DITTI			0	30
8		Lowest		0	30
9	DECIMAL	0~4(from right	30~34	2	32
	POINT	to left)			
10	XOR	HIGH 4 BITS		XOR=0X1	31
11	RESULT	LOW 4 BITS		В	42
12	STOP	XOFF	03	XOFF	03
XOR=2⊕	3 ⊕ 4 ⊕ 5 ⊕ 6	⊕7⊕8⊕9			

GROUP NO.	CONTE	NT NOTES	EXA	MPLE
CONTENT		NOTE	CONTENT	CODE (HEX)
1	START	XON(02)	XON	02
2	ADDRESS	A~Z	ADD=1	41
3	COMMAND	A:FOR SHARKE	FOR	41
	(FROM A~H)	B:FOR GROSS W	EXAMPLE:	
		C:FOR TARE W	COMMAND A	
		D:FOR NET W		
		E:FOR TRUCK NO.		
		F:FOR GOODS NO.		
		G:FOR CUSMR NO.		
		H: FOR NOTE NO.		
4	VERIFY	HIGH 4 BITS	XOR	30
5		LOW 4 BITS		30
6	STOP	03(XOFF)	XOFF	03
NOTE: XOR=2	2 ⊕ 3			

B. Command mode

Indicator will act according to instruction from computer, one instruction from PC will trigger one operation at indicator, please refer to following table for instruction format from PC:

Indicator will response PC as followed format:

GROUP NO		NOTES	EXA	MPLE
			CONTENT	CODE (HEX)
1	STAR	T XON (02)	XON	02
2	ADDR	ESS: A~Z	A	41
3		A:To SHARKE	A	41
	A~H	B:To send GROSS W		
	C:To send TARE W			
		D:To send NET W		
		E:To send TRUCK NO.		
		F:To send GOODS NO.		
		G:To send CUSTOMER NO.		
		H:To send NOTE NO.		
	EOT (0X04):		
4	COOR	ESPONDING DATE ACCORDING	REFER TO F	OLLOWED
	TO C	OMMAND	TABLE	
N				
N+1	HIGH	4 BITS OF XOR	XOR=00	30
N+2	LOW	4 BITS OF XOR		30
N+3	03 (X	OFF) STOP		03
NOTE1:XOR	k=2 ⊕ 3	3 ⊕ (N-1) ⊕		

NOTE: Address 1~26 corresponds ASCII CODE of A~Z, that is to say, when PC communicates with indicator, the address in the instruction from PC just corresponds ACSII code of A~Z as followed table listed:

_	1			ı			
Adr	А	DDRES	S	Adr	А	DDRES	S
No.	Address	ACSII CODE		No.	ADDRESS	ACS	II CODE
		HEX	DECIMAL			HEX	DECIMAL
01	А	41	65	14	N	4E	78
02	В	42	66	15	0	4 F	79
03	С	43	67	16	Р	50	80
04	D	44	68	17	Q	51	81
05	E	45	69	18	R	52	82
06	F	46	70	19	S	53	83
07	G	47	71	20	Т	54	84
08	Н	48	72	21	U	55	85
09	I	49	73	22	V	56	86
10	J	4A	74	23	M	57	87
11	K	4B	75	24	X	58	88
12	L	4C	76	25	Y	59	89
13	М	4D	77	26	Z	5A	90

Content of $4 \sim N$ is as followed table according to different command:

COMMAND A	NO DATA	ONE FRAME (6 GROUPS)
COMMAND B	A: Sign bit(+/-)	ONE FRAME (14 GROUPS)
B:To send GROSS W	B: Highest bit (6 BITS)	
	(from high to low)	
	G:	
	H:DECIMAL POINT(0~4)	
COMMAND C	A: Sign bit(+/-)	ONE FRAME (14 GROUPS)
C:To send TARE W	B: Highest bit (6 BITS)	
	(from high to low)	
	G:	
	H:DECIMAL POINT(0~4)	
COMMAND D	A: Sign bit(+/-)	ONE FRAME (14 GROUPS)
D:To send NET W	B: Highest bit for g.w	
	(from high to low)	
	G:	
	H:DECIMAL POINT(0~4)	
COMMAND E	A:First bit for truck no.	ONE FRAME (11 GROUPS)
E:To send TRUCK NO	B:	
	C:	
	D:	
	E:Last bit for truck no.	
COMMAND F	A:First bit for goods no.	ONE FRAME (9
To send GOODS NO.	В:	GROUPS)
	C: Last bit for goods no.	

COMMAND G	A:First bit for customer	ONE FRAME (9
To send CUSTOMER NO.	no.	GROUPS)
	B:	
	C:Last bit for customer	
	no.	
COMMAND H	A:First bit for note no.	ONE FRAME (9
To send NOTE NO.	B:	GROUPS)
	C: Last bit for note no.	
ERROR(0X04)	NO DATA	1 FRAME(6 GROUPS)

Notel:For verify of XOR

High 4 bits and low 4 bits of XOR is defined: if high 4 bits or low 4 bits of XOR is ≤ 9 , then add 30h and transmit in ASCII code; if high 4 bits or low 4 bits of XOR is >9, hen add 37h and transmit in ASCII code

Note2:

Parameter setting at indicator for communication with PC
There are mainly three parameters to be set for communication with PC, they are address, baud rate and communication method.
Refer to followed table for setup parameter for communication:

Step	Operation	Display	Note
1		[PSt 00]	Press[parameter] and

	Press[paramet er] Press[1] Press[INPUT]	[PSt 01]	1, directs to communication parameter type set				
2	Press[INPUT]	[P1 00]	Input parameter no. (0~2) For example:00				
3 No.00	Press[1] Press[INPUT]	[Adr **] [Adr 01]	Parameter NO.00 is for set address				
4 No.01	Press[3] Press[INPUT]	[bt *] [bt 3]	Baud rate(0~3) 0:600;1:1200 2:2400;3:4800				
5 No.02	Press[0] Press[INPUT]	[tF *] [tF 0]	Communication method (0~1) 0: Continuous 1: On command				
6		Set for parameter type communication finish, return to weighing status;					

4.2.2 Connect to Scoreboard

Data is transmitted serially in binary code with baud rate 600. Data format is as listed below (one group):

0	1	2	3	4	5	6	7	8	9	10			
START		DA:	ΓΑ(Low	is pr	ior to	DATA(Low is prior to high)							

Indicator sends one frame data to scoreboard per 100ms, one frame consists of 3 groups while the data format of one group is as listed above. Below is the content for one frame:

	0	1	2	3	4	5	6	7	8	9	10
Group		D0	D1	D2	D3	D4	D5	D6	D7	SIGN	STOP
1	Start		Х		7	ď	G18	G16	G17	0	1
	0	1	2	3	4	5	6	7	8	9	10
Group		D0	D1	D2	D3	D4	D5	D6	D7	SIGN	STOP
2	Start	G8	G9	G10	G11	G12	G13	G14	G15	0	1
Group	0	1	2	3	4	5	6	7	8	9	10
3		D0	D1	D2	D3	D4	D5	D6	D7	SIGN	STOP
	Start	G0	G1	G2	G3	G4	G5	G6	G7	1	1

For group one, Sign bit is 0; X(D0,D1,D2) means decimal point $(0\sim4)$; Y(D3) means sign(1 for negative while 0 for positive); Y(D4) for back up; G18,G17 and G16 is binary code; For group two, Sign bit is 0; G15~G8 is binary code; For group three, Sign bit is 1; G7~G0 is binary code;

From $G0\sim G18$ consists of 19 bit binary code, low prior to high with content of weighing data(net weight)

4.3 Connection to Printer



25-pin interface

PIN #	ASSIGNMENT	PIN #	ASSIGNMENT
1	ST	7	D5
2	D0	8	D6
3	D1	9	D7
4	D2	11	BUSY
5	5 D3		GND
6	D4		

Description for each pin is as listed in above table. Before print operation, first set up parameter for print function, then connect indicator to printer with printer cable. Becasue printer parameter set will effect print content and data save format, be sure to refer to followed table carefully for parameter setting:

Step	Operation	Display	Note
1	Press[paramete r] Press[2] Press[INPUT]	[PSt 00] [PSt 02]	Press[parameter] and 2, directs to print parameter type
2	Press[INPUT]	[P2 00]	Input parameter no. For example:00
3 No.00	Press[0] Press[INPUT]	[Aut0 *] [Aut0 0]	Select Auto/Manual(0~2) 0-Manual 1-Auto(invalid when turn on next time) 2-Auto(valid when turn on text time)

			,
4 No.01	Press[2] Press[INPUT]	[tyPE *] [tyPE 1]	Print type selection 0: Print invalid 1: Built-in printer 2: EPSON LQ-300K(Recom) 3: Panasonic KX-P1131; 4: Panasonic KX-P1121
5	Press[99]	[HL **]	Print only when: 00-Back to zero 25-Back to <25% F.S. 50- Back to <50% F.S. 75- Back to <75% F.S. 99- Even it's F.S
No.02	Press[INPUT]	[HL 99]	
6	Press[3]	[Arr *]	Page ² at linked-format (1~3) 1:1 page 2:2 page 3:3 page
No.03	Press[INPUT]	[Arr 3]	
7	Press[1000]	[L ******]	Min. weight for auto printing (no less than 10 d)
No.04	Press[INPUT]	[L 001000]	
8	Press[3]	[b **]	Printing rows in linked format (0~30)
No.05	Press[INPUT]	[b 03]	
9	Press[1]	[odE *]	Print format(0~6) 0: Record format 1: Linked-format(upright) 2: Linked-format(across) 3: Record format(user defined)
No.06	Press[INPUT]	[odE 1]	

² This set is valid when No.06 parameter (print format) is set as 1,2,4,5

			4: Linked-format(upright, user defined) 5: Linked-format(across, user defined) 6: Filled-in format
10 No.07	Press[0] Press[INPU T]	[dct *] [dct 0]	Discount rate select in filled-in format (0~1) 0: Without discount rate 1: With discount rate
11 No.08	Press[1111] Press[INPU T]	[Uy *****] [Uy 11111]	Save option, (Non 0 number will be regarded as 1 when set the value of this parameter ³)
12 No.09	Press[1111] Press[INPU T]	[Hy *****] [Hy 11111]	Print content selection: to print out no. or detailed content ⁴
13 No.10	Press[1100 00] Press[INPU T]	[y *****]	Print control parameter ⁵
14 No.11	Press[0] Press[INPU T]	[Ut *] [Ut 0]	Weigh unit select (0~1) 0: kg; 1: t
15 No.12	Press[1] Press[INPU T]	[Pd *] [Pd 1]	Brightness of font at built in printer, more bigger, more bright

³ For parameter Uy, there are 5 bits, from left to right, it corresponds 1~5, definition for each bit is as followed:

Bit 1 for company name: 0 not use; 1 use

Bit 2 for note: 0 not use; 1 use

Bit 3 for customer: 0 not use; 1 use Bit 4 for cargo no.: 0 not use; 1 use Bit 5 for truck no.: 0 not use; 1 use

Bit 1 for company name: 0 not print; 1 print company content

Bit 2 for note: 0 print note no.; 1 print note content

Bit 3 for customer: 0 print customer no.;1 print customer content

Bit 4 for cargo no.: 0 print cargo no.;1 print cargo content

Bit5:back up

Bit 1 for print speed: 0 normal; 1 fast

Bit 2 for table frame: 0 not print table frame.; 1 print table frame

Bit 3 for note when save and print: 0 current note no..;1 input note no.

Bit 4 for customer when save and print: 0 current customer no..;1 input cust no.

Bit5: for cargo when save and print: 0 current cargo no..;1 input cargo no.

Bit 6: for truck when save and print: 0 current truck no..;1 input truck no.

⁴ For parameter Hy, there are 5 bits, from left to right, it corresponds 1~5, definition for each bit is as followed:

⁵ For parameter y, there are 6 bits, from left to right, it corresponds 1~6, definition for each bit is as followed:

16 No.13	Press[0111 1] Press[INPU T]	[y² wxyz [y² 011:	Z] A	Working mode selection: W bit: power save 0=Close 1=Open X bit:Print or not 0=Save but not print 1=Save and print Y bit:Save time 0=First time weighing 1=Second time weighing Z bit: axle weighing mode 0=Close 1=Open	
17 No.14	Press[01] Press[INPU T]	[AC	XX]	(00~99),	
18	Set for parameter type print finish, return to weighing status;				

5. Calibration and password setting

A, Calibration

First connect indicator to load cell properly so that indicator will work properly, it's better to calibrate after $15\sim30$ minutes when it is powered on. Then open the calibration board at the back of indicator, you will see the calibration switch, turn the switch to top, then you could calibrate as followed table:

step	Operation	Display	Note
1	Press [cali]		

2	Press	[888888]	[c000000]	888888 is password for
	Press	[input]	[c*****	calibration, you could change
				refer to followed table
3	Press	[10]	[E ***]	Input division
	Press	[input]	[E 010]	1/2/5/10/20/50/100
4	Press	[0]	[dc *]	INPUT decimal point (0-4)
	Press	[input]	[dc 0]	Example:Owithout Decimal
				point
5	Press	[124]	[Pn VWXYZ]	INPUT Parameters value: 6
	Press	[input]	[Pn 00124]	V: Application (0-1)
				0: Non Commercial
				1: Commercial
				W:Zero track speed(0~3)
				X: Zero track range (0~9)
				Y:Manual zero range(1~5)
				Z:Auto zero range(1~5)

6

W	0	1	2	3						
/S	0.4	0.3	0.2	0.1						
X	0	1	2	3	4	5	6	7	8	9
	NO	0.5e	1.0e	1.5e	2.0e	2.5e	3.0e	3.5e	4.0e	4.5e
Y,Z	1	2	3	4	5					
F.S	2%	4%	10%	20%	100%					

Press [1] [Flt *] Flt for filter intensity(0~4) Press [input] [Flt 1] intensity(0~4) Normally, choose 0, more serious the weighing environment it is, the bigger value it should be [F ******] F value is full capacity [0] [5] [0] [F value, then press [Input]; press [input] 060000] Directly to step 11 if press [Input]; back to weighing status if press[weigh] 7 press [Input] [noLoadn] Zero point calibration, press [input] when the stable light is on and assure it's unloaded, wait for 5~10 seconds Press [10000] [AloAd1] Load the weight, and input the					
Normally, choose 0, more serious the weighing environment it is, the bigger value it should be [F******] F value is full capacity press [6] [0] [0] [5][0] [F value, then press [Input]; press [input] 060000] Directly to step 11 if press [Input]; back to weighing status if press[weigh] 8 press [Input] [noLoadn] Zero point calibration, press [input] when the stable light is on and assure it's unloaded, wait for 5~10 seconds	6	Press	[1]	[Flt *]	Flt for filter
serious the weighing environment it is, the bigger value it should be 7		Press	[input]	[Flt 1]	intensity(0~4)
environment it is, the bigger value it should be [F******] F value is full capacity If need calibration, INPUT F [0] [5][0] [F value, then press [Input]; press [input] 060000] Directly to step 11 if press [Input]; back to weighing status if press[weigh] 7 Press [Input] [noLoadn] Zero point calibration, press [input] when the stable light is on and assure it's unloaded, wait for 5~10 seconds					Normally, choose 0, more
value it should be					serious the weighing
[F*****] F value is full capacity press [6] [0] [0] [5] [0] press [input] 060000] Directly to step 11 if press [Input]; back to weighing status if press[weigh] 7 8 press [Input] [noLoadn] Zero point calibration, press [input] when the stable light is on and assure it's unloaded, wait for 5~10 seconds					environment it is, the bigger
press [6] [0] [0] [5][0] [F value, then press [Input]; press [input] 060000] Directly to step 11 if press [Input]; back to weighing status if press[weigh] 7 8 press [Input] [noLoadn] Zero point calibration, press [input] when the stable light is on and assure it's unloaded, wait for 5~10 seconds					value it should be
[0] [5][0] [F value, then press [Input]; press [input] 060000] Directly to step 11 if press [Input]; back to weighing status if press[weigh] 7 8 press [Input] [noLoadn] Zero point calibration, press [input] when the stable light is on and assure it's unloaded, wait for 5~10 seconds	7			[F *****]	F value is full capacity
press [input] 060000] Directly to step 11 if press [Input]; back to weighing status if press[weigh] 7 8 press [Input] [noLoadn] Zero point calibration, press [input] when the stable light is on and assure it's unloaded, wait for 5~10 seconds		press	[6][0]		If need calibration, INPUT F
[Input]; back to weighing status if press[weigh] ⁷ 8 press [Input] [noLoadn] Zero point calibration, press [input] when the stable light is on and assure it's unloaded, wait for 5~10 seconds		[0]	[5][0]	[F	value, then press [Input];
status if press[weigh] 7 8 press [Input] [noLoadn] Zero point calibration, press [input] when the stable light is on and assure it's unloaded, wait for 5~10 seconds		press	[input]	060000]	Directly to step 11 if press
8 press [Input] [noLoadn] Zero point calibration, press [input] when the stable light is on and assure it's unloaded, wait for 5~10 seconds					[Input];back to weighing
press [input] when the stable light is on and assure it's unloaded, wait for 5~10 seconds					status if press[weigh] 7
press [input] when the stable light is on and assure it's unloaded, wait for 5~10 seconds					
light is on and assure it's unloaded, wait for 5~10 seconds	8	press	[Input]	[noLoadn]	Zero point calibration,
unloaded, wait for 5~10 seconds					press [input] when the stable
seconds					light is on and assure it's
					unloaded,wait for 5~10
9 Press [10000] [AloAd1] Load the weight, and input the					seconds
9 Press [10000] [AloAd1] Load the weight, and input the					
	9	Press	[10000]	[AloAd1]	Load the weight, and input the
Press [10000] value of weight when stable		Press		[10000]	value of weight when stable
[input]/[check light is on.		[input]/[check		light is on.

⁷ If full capacity is more than 65000, then division must be no less than 5
--

]		For example:10000			
	Press [check] if need nonlinearity correction, it directs to step 10 and step 11; if no need for nonlinearity correction, then it directs to step 12					
10	Press [20000] Press [input]/[che ck]	[AloAd2]	Load the weight, and input the value of weight when stable light is on, be sure weight loaded at this step must be more than the last one, press [<-] to the former calibration point For example:20000			
			Point 2,3,4,5 must be higher than the former one			
12	Press [input] Press [input] Press [input] Press [input] Press [input] Press [input]	[A *****] [L *****] [LH **.**] [b ******] [O ******] [C ******] [t ******] [tH **.**] [d ******]	Show calibration rate, don't modify it, press [weigh] to exit calibration status			

	Press [input] Press [input]	[UH **.**] [E ******] [Y ******]	
13	Press[1] Press[INPUT]	[Adr **] [Adr 01]	For communication address
14	Press[1] Press[INPUT]	[bt *] [bt 1]	Baud rate(0~4) 0:600; 1:1200;2:2400;3:4800;4:9600
15	Press[0] Press[INPUT]	[tF *] [tF 0]	0-Continous sending 1-On command
16		Weighing status	Calibration finish Turn the calibration switch to bottom so that it would work properly

Notel:Calibration rate could be printed out when finished, press[report], press [8][0], press [input] to save and print.

Keep these data in case calibration rate is lost, you could just input without recalibration again.

Operation for password administration:

Password administration includes three parts:

- ◆Encrypt operation
- ◆Password change
- ◆Password unlock

Password change is for calibration and encrypt. The default password for calibration and other function is "888888", user could change any other password except "000000", operation is as followed table:

!Be sure to keep the calibration password you set. Lost of calibration password will lend no way to calibrate. When the calibration is lost, you could solve as followed:

◆Step 1, get a temporary unlock code

	Г		T
step	Operation	Display	Note
1	Press	[PSt 00]	Input parameter type 20
	[parameter]	[PSt 20]	for change for
	Press [20]		calibration password
	Press [input]		
2	Press [888888]	[0 000000]	Input old calibration
	Press [input]	[0 888888]	password 888888
3	Press [1111]	[UP WXYZ]	Input value for encrypt
	Pres [input]	[UP 1111]	parameter ⁸
4	Press [123456]	[n 000000]	Input new
	Press [input]	[n 123456]	password, password can be
			any no. except 000000
5	Press [123456]	[r 000000]	Reconfirm
	Press [input]	[r 123456]	
		[PASS]	Weighing status

Turn the calibration switch to top, and operate as followed table:

◆Step 2, Forward this code this sales staff, then sales staff could offer you a temporary password with the code you offer

◆ Step 3, Calibrate or change the password again with the

step	Operation	Display	Note
1	Press	[PSt 00]	Input parameter type 22
	[parameter]	[PSt 22]	for unlock code view
	Press [22]		
	Press [input]		
2	Press [input]	[r *****]	Write down this code
3		Weighing	
		status	

temporary password.

B.Parameter setting

- Parameter Review

Press [parameter] key, indicator displays [PST 00], input the parameter type one want to set, then press [INPUT] key, it will directs you to the corresponding parameter setting.

Press [INPUT] key to confirm the set up and directs to the next parameter (if there is no more parameter for a certain parameter type, then indicator returns to weighing status);

Press [WEIGH] key to exit parameter setting and back to weighing status, the last parameter setting won't be saved;

Press [CHECK] key to the last parameter without saving the current parameter setting;

-Followed table is the parameter type list:

Type no.	Туре
00*	For calibrate
01	For communication
02	For printing
03	Back up
04	Back up
05~09	Back up
10	Edit content of a certain goods no.
11	Edit content of a certain customer no.
12	Edit content of a certain note no.
13	Edit to be printed customer name
14	For user-defined data format
15	For define for format of weighing bill
16~19	Back up
20*	For change of calibration password
21~27	Back up
28	For display for inner code
29	Back up
30	Download from PC
31~39	Back up
40	Clear all goods content for all no.
41	Clear all customer content for all no.
42	Clear all note content for all no.
43	Clear content for to be printed customer
44~48	Back up
49	For clear all content(goods, customer)
50	Back up
51	For initial communication parameter
52	For initial printer parameter

Type no.	Туре		
53~99	Back up		
Parameter	with * needs calibration password before set up		

- Parameter initialization:

Due to various parameters, it's better to do initialization for all parameters, then set the parameter user concerned according to the manual:

Step	Operate	Display	Note
1	Press[parameter] Press[51] Press[INPUT]	[PSt 00] [PSt 51]	Input parameter type no. 51 : Communication parameter 52: Print parameter
*2	Press[888888] Press[INPUT]	[c 000000] [c 888888]	Turn on calibration switch, input calibration password "888888" Note: calibration password can be changed default is "888888"
3	Press[1] Press[INPUT]	[surE 0] [surE 1]	Confirm initialize or not 0: Not initialize 1: Initialize
4		Weighing status	Initialization finish, exit parameter setting mode

6. Operation

6.1 Power on and auto zero

A, Turn on , indicator will perform "999999-000000" self check and display [ver *.*] then come into weighing status.

B, Whe power on, if weighs on platform deviates from zero point but within auto zero range, indicator will perform auto zero.

6.2 Manually zero

A, Press [Zero], indicator will be back to zero, and zero light will be on;

B, Zero key will only be valid when weighs on platform is within manual zero range;

C, Zero operation is valid only when stable light is on

6.3 Tare operation

There are three methods to tare:

Method 1, Normal tare

Press [tare] key when weighing data is positive and stable, the displayed weighing data will be regarded as tare weight, then indicator will display 0 and tare light is on Method 2, Pre-tare

Press [Pre tare] key at weighing status, indicator will display [P *****], the displayed data is the former tare weight. If need to set new tare weight, just input by numeric key, press [input] to confirm.

Method 3, Call tare weight according to truck no.

Press [truck no.] at weighing status, indicator display [0 *****], input truck no. by numeric key, press [tare] key, then indicator will find the corresponding tare weight of the truck no. for use.

-At weighing status, continuous tare operation is permitted. When tare weight is 0, then tare light will be off; when indicator within manual zero range, press [zero] to make tare weight as 0, the tare light is also off.

-Press [gross/net] key to switch between gross weight display and net weight display

6.4 Set for date and time

A, Indicator displays the present date and "date"

light is on if you push [Date] key at weighing status.

If the date is correct, you can exit by pressing

[Input]or [weigh] key. If the date is not correct,

Input the correct date by numerical key, then press

[Input] key for confirm. Then indicator will display current

Time, then

B, If the time is correct, you can exit by pressing [Input]or [weigh] key. If the time is not correct, Input the correct time by numerical key, then press [Input] key for confirm.

6.5 Internal code display

A, The indicator will display the internal code if you press [parameter] key and input [2], [8] at weighing status, at this time the decimal point after the last number is on. You can exit the "internal code" status by pressing [paraemter] key again, and input [2], [8], the decimal point after the last number will be off.

B, At internal code display status, all other keys are invalid except [zero], [parameter]

C, 20 internal codes is equal to one division

6.6 Static axis weighing

Please refer to followed table about how to set the indicator so that it could work in axis weighing work mode. Before set, assure to set parameter yA as 1 to activate axis weighing function:

Step	Operate	Display	Note
1	Press [axle]	[*****]	Single axle or axles are all at scale and truck stop, weighing data is stable
2	Press [axle]	[L*****] [L*****	Current axle weight is locked, next axle or axles come to scale, weighing data change is more than Ac%*loacked

			weight, former lock is cancelled, truck stops
3	Repeat step 2, until all axles are passed through, press[axle all]	 [L*****]	Display weight for total, able to save and print
4	Press [axle all]	[*****]	Unlock the data, back to weighing status

7.Save and print

- 7.1 Save for weighing records
- For truck no., it's 5-bit number $(1\sim99999)$, for goods no., it's 3-bit number $(0\sim200)$, for customer no, it's a 2-bit number $(0\sim99)$, for note no., it's a 2-bit number $(0\sim99)$.
- ◆Max. weighing records is 1501, when it's full, the first one will be auto deleted;
- ◆Max. truck no. and corresoponding quantity is 1500, when it's over, it will display [Err 10]
- ◆For goods name, customer name, note info, the length is 10 English character
- ◆Each time one weighing record is saved, then indicator will print out one weighing record(when print set up is valid)

- ◆There are three methods to save:
- -Method 1, two times weighing to consist of one weighing record, use [save print 2] to save
- Method 2, one time weighing to consist of one weighing record when tare weight is known, use [save print 1] to save
- Method 3, what weighs is just goods, then one time weighing consist of one weighing record, use [save print 2] to save

Rule for differ for above 3 methods is as followed:

- --When truck no. is 00000, then save method is 3
- --When tare light is on, then save method is 2
- --When truck no. is any no. except 00000 and tare weight is off, then save method is 1
- 7.2 Save operation for [save print 1] and [save print 2]
- ◆[save print 1], one time weighing, save and print, operate as followed table:

	•	1	1
step	Operation	Display	Note
1	Press [save		Weighing status and
	print 1]		data stable
2	<pre>Input truck no. Press [input]</pre>	[o *****] [o 03217]	input track no
3	Input goods no. Press [input]	[hn **] [hn 35]	Input goods no.: 35
4	<pre>Input customer no. Press [input]</pre>	[cn **] [cn 45]	Input customer no.:45
5	Input note no. Press [input]	[bn **] [bn 67]	Input note no.:67
6	Input [10] Press [input]	[BFL **] [BFL 10]	<pre>Input discount rate in pertentage:10%</pre>
7	III a a a a i ah i a a da	[saue]	<pre>[prnt] for print;[saue] for not print able, or gross weight</pre>

Note1: When weighing data is unstable, or gross weight is ≤ 0 or net weight is ≤ 0 , data can't be saved

◆[save print 2], two times weighing, save and print, operate as followed table:

step	Operation	Display	Note
1	Press [save		Weighing status
	print 2]		
2	Input truck no.	[0 *****]	Input truck no.: 03217
	Press [input]	[0 03217]	
3		[hn **]	Input goods no.: 35
	Input goods no.	[hn 35]	
	Press [input]		
4	Input customer	[cn **]	Input customer
	no.	[cn 45]	no.:45
	Press [input]		
5	Input note no.	[bn **]	Input note no.:67
	Press [input]	[bn 67]	
6		[BFL **]	Input discount rate
	Input [10]	[BFL 10]	in pertentage:10%
	Press [input]		
7		[prnt] or	[prnt] for
		[saue] or	print; [saue] for not
		[load]	print;[load] save
			for first time during
			two times weighing

Note1: When weighing data is unstable, or gross weight is ≤ 0 or net weight is ≤ 0 , data can't be saved Note2: Please refer to appendix for more operations

7.3 Save for truck no. and tare weight

Method1,

step	Operation	Display	Note
1	Press [truck		Weighing status
	no.]		
2	Input truck no.	[0 *****]	Example:To send
	Press [input]	[o 35790]	35790
3	Input tare weight Press [input]	[p*****] [p01000]	Example:To send
			Save finish

Method2,

Press[truck no.] and input truck no. when unloaded truck is on and stable light is on, then press [preset tare]
-Method 3,

When save a weighing record, if the tare weight for the truck no. isn't saved before, then regard tare weight at this record as the tare weight of the truck.

7.4 Print operation

- ◆Before print, first set up the parameter concerned to printing
- ◆Print while save, press [save pint 1] or [save print 2], it will save one weighing record and print this record(if print set up is valid, that is to say, print type is not zero and choose print while save
- ◆Press [supply print] to print out current record in memory after problem for former print is sovled
- ◆Press [total print] to print out the accumulation value after a period's weighing is finished
- ◆If press [print save 2], first unload then load or first load then unload, for the first time record is saved, it just display [load] for 1.5 seconds but not print, but if press [supply print], it can print out the uncomplete record
- ullet When FS is \leqslant 65000, then max.accumulation is 16777214 (no decimal point)

- ullet When FS is >65000, then max. accumulation is 83886070 (no decimal point)
- ◆For more examples, please refer to appendix
- ◆User-defined print format:

There are two user-defined formats, one is linked format, the other is record format, set step as followed table:

Step	Operate	Display	Note
1		[PSt	Input parameter type
	PRESS[Parameter]	00]	no.
	PRESS[1][4]	[PSt	14: User-defined,
	PRESS[INPUT]	14]	record format (linked-
			format,across;
			general lists)
			15:
			User-defined,linked
			format-upright)
2		[P14	Row(column) number to
	PRESS[input]	00]	set
			00 for first
			row(column)
3		[ALO	Input print content
	PRESS[1]	**]	for first row(column)
	PRESS[INPUT]	[AL0	
		01]	

4		[AL1	Input print content
	PRESS[2]	**]	for second row(column)
	PRESS[INPUT]	[AL1	
		02]	
5		[AL2	Input print content
	PRESS[3]	**]	for third row(column)
	PRESS[INPUT]	[AL3	
		03]	
•••	•••	•••	•••
6		[AL9	Input print content
	PRESS[0]	**]	for tenth row(column)
	PRESS[INPUT]	[AL9	
		00]	
7			Back to weighing
			status

Note: Indicator supports max.10 rows(columns) user-defined input, print content defined as followed:

00: Not print

01: Serial no.

02: Date

03: Time

04: Truck no.

05: Goods no.

06: Gross weight

07: Tare weight

08: Net weight

09: Customer

10: Note

 $11: \mathsf{Date}/\mathsf{Time}$ (Valid only when user-defined situation)

For example:

Serial no.	Time	Truck no.	Net weight
0001	12. 00. 00	12345	3. 000kg

Then set parameter ALO AS "01", AL1 as "03", AL2 as "04", AL3 as "08", AL4 \sim AL9 as "00"

◆Print for stat. report

Indicator can print report include all weighing records, report include weighing records that meet some requirement or report include weighing records group by some key words (only outside printer support this function)

◆Procedure for set stat. report

A, Press [format print], indicator display [Pb 00], select the report format code(refer to followed table), then press [INPUT], then input requirement such as date, truck no. and so on. Then indicator begins to print.

Code	Code note
0.0	Report include all weighing records
01	Report include weighing records for one date
02	Report include weighing records for one date period
03	Report include weighing records for one truck no.
04	Report include weighing records for one goods no.
05	Report include weighing records for one customer
06	Report include weighing records for one note
09	Report include weighing records that meet requirement for date, date period, truck no.goods no.customer and note)
10	Report include all weighing records in user defined format
11	Report include weighing records for one date in user defined format
12	Report include weighing records for one date period in user defined format
13	Report include weighing records for one truck no. in user defined format
14	Report include weighing records for one goods no. in user defined format
15	Report include weighing records for one customer in user defined format
16	Report include weighing records for one note in user defined format
19	Report include weighing records that meet requirement for date, date period, truck no.goods no.customer and note) in user defined format
20	Report include all truck no.
21	Report include all goods no.
22	Report include all customer
23	Report include all note
30	Report include all truck no.for one date
31	Report include all goods no. for one date

32	Report include all customer for one date
33	Report include all note for one date
40	Report include all truck no.for one date period
41	Report include all goods no. for one date period
42	Report include all customer for one date period
43	Report include all note for one date period
80	Print calibration parameter
81	Print communication parameter
82	Print print parameter
83	BACK UP
84	
89	Print all parameters
90	Print goods no. and goods name
91	Print customer no. and customer name
92	Print note no. and note info.
93	Print company name
99	Print all info. and company name

◆Example for print above reports

-Operation to print report code 9 as listed in above table

Step Operate Display Note	ds that nt ment
report	ds that nt ment
PRESS[9] meet requirement [E 000000] Select requirement PRESS[111111] [E 111111] Note 1 PRESS[INPUT] [d **.**.**] PRESS[40101] [d 04.01.01] Input date or of the select requirement of the select re	ment
PRESS[9] meet requirement press[INPUT] [E 000000] Select requirement press[INPUT] [E 111111] Note 1 PRESS[INPUT] [d **.**.**] PRESS[40101] [d 04.01.01] Input date or	ment
[E 000000] Select requirer Note 1 PRESS[INPUT] [d **.**.**] PRESS[40101] [d 04.01.01] Input date or	
2 PRESS[111111] [E 111111] Note 1 PRESS[INPUT] [d **.**.**] PRESS[40101] [d 04.01.01] Input date or or	
PRESS[INPUT] [d **.**.**] PRESS[40101] [d 04.01.01] Input date or	date
[d **.**.**] PRESS[40101] [d 04.01.01] Input date or or	date
PRESS[40101] [d 04.01.01] Input date or of	date
13 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	date
PRESS[INPUT] period start da	
	ay
[A **.**.**]	
PRESS[40201] [A 04.02.01] Input date peri	iod stop
PRESS[INPUT] day	
[0 ****]	
5 PRESS[1234] [o 01234] Input truck no	
PRESS[INPUT]	
[Hn 000]	
6 PRESS[123] [Hn 123] Input goods no	
PRESS[INPUT]	
[cn 00]	
7 PRESS[45] [cn 45] Input customer	no.
PRESS[INPUT]	
[bn 00] Input note no.	
8 PRESS[67] [bn 67]	
PRESS[INPUT]	
9 [Prnt] Begin to print	report

Note 1: Pareamter E has 6 bits, from left to right, each bit is defined as followed:

Bit 1 for note no.: 0 not input; 1 input
Bit 2 for customer no.:0 not input; 1 input
Bit 3 for goods no.:0 not input; 1 input
Bit 4 for truck no.:0 not input; 1 input
Bit 5 for date period: 0 not input; 1 input
Bit 6 for date: 0 not input; 1 input

If one of above bit chosen as not input, then concerning step in above table will be skipped;

7.5 Check operation

- ◆Press [check] to view all kinds of memorized information, operation is as followed:
- ◆Press [check] at weighing status(if encrypt is required for check operation, then indicator display [c 000000] to indicate user to input password). If password is input correctly, indicator display [rEAd 1] to indicate information type:

[rEAd	1]	Check by date	[rEAd 2]	Check by truck no.
[rEAd	3]	Check by goods no.	[rEAd 4]	Check by customer no.
[rEAd	5]	Check by note no.	[rEAd 6]	Check truck no.

After input check method(1~6 as listed above), indicator would indicate user to input requirement, then it would display the record one by one.Press [<-] or [->], it would display next record.

7.6 Delete operation

There are several ways to delete:

- Method 1, delete all records (include truck no. and tare weight)
- Method 2, delete one truck no. and corresponding tare weight, and all weighing records related to this truck no.
- -Method 3, Delete the last saved records
- -Method 4, Delete records related to a certain date
- -Method 5, Delete weighing records related to one certain truck no., but save record for truck no. and tare weight of it -Method 6, Delete weighing records related to one certain goods no.
- -Method 7, Delete weighing records related to one customer no.
- -Method 8, Delete weighing records related to one note no.
- -Method 9, Delete any weighing record
- ◆Any method to delete the record, indicator would display [Sure 0] to let user confirm. If sure is non zero, press [input] to confirm; if sure is zero, press [input] to exit
- ◆Operation

- -For method 1, press[delete] at weighing status, (if delete encrypt is required, then it indicates to input the password), it would display [sure 0], press 1 and [input] to delete all records:
- -For method 2, press [truck no.], indicator display [o ******], input truck no. and [delete]
- -For method 3, press [delete], indicator display [sure 0], press [9] and [input]
- -For method 4,press [check], indicator display [rEAd 1],press [input],indicator display [d ******],input the date you want to delete,press [delete]
- -For method 5, press [check], indicator display [rEAd 1], press [2] and [input], indicator display [o ******], input the truck
- no.you want to delete, press [delete]
- -For method 6, press [check], indicator display [rEAd 1], press
- [3] and [input], indicator display [Hn ***], input the goods no you want to delete, press [delete]
- -For method 7, press [check], indicator display [rEAd 1], press
- [4] and [input], indicator display [Cn ***], input the customer
- no you want to delete, press [delete]
- -For method 8, press [check], indicator display [rEAd 1], press
- [5] and [input], indicator display [bn ***], input the note no vou want to delete, press [delete]

- -For method 9, when indicator displays one record, press [delete] to delete the diplayed record.
- ◆Method 2~9, doesn't lead real deletion to release the memory size it takes, only method 1 leads to real deletion.
- ◆Pay attention when act delete operation

	AS	SCII		AS	CII	_	AS	CII	_	AS	SCII
С	DEC	HEX	С	DEC	HEX	С	DEC	HEX	С	DEC	HEX
NUL	00	00	SP	32	20	@	64	40	` `	96	60
SOH	01	01	!	33	21	Α	65	41	а	97	61
STX	02	02	"	34	22	В	66	42	b	98	62
ETX	03	03	#	35	23	С	67	43	С	99	63
EOT	04	04	\$	36	24	D	68	44	d	100	64
ENQ	05	05	%	37	25	Е	69	45	е	101	65
ACK	06	06	&	38	26	F	70	46	f	102	66
BEL	07	07	,	39	27	G	71	47	g	103	67
BS	08	08	(40	28	Н	72	48	h	104	68
Н	09	09)	41	29	I	73	49	i	105	69
LF	10	0A	*	42	2A	J	74	4A	j	106	6A
VT	11	0B	+	43	2B	K	75	4B	k	107	6B
FF	12	0C	,	44	2C	L	76	4C	I	108	6C
CR	13	0D	-	45	2D	М	77	4D	m	109	6D
SO	14	0E		46	2E	N	78	4E	n	110	6E
SI	15	0F	/	47	2F	0	79	4F	0	111	6F
DLE	16	10	0	48	30	Р	80	50	р	112	70
DC1	17	11	1	49	31	Q	81	51	q	113	71
DC2	18	12	2	50	32	R	82	52	r	114	72
DC3	19	13	3	51	33	S	83	53	S	115	73
DC4	20	14	4	52	34	Т	84	54	t	116	74
NAK	21	15	5	53	35	U	85	55	u	117	75
SYN	22	16	6	54	36	V	86	56	V	118	76
ETB	23	17	7	55	37	W	87	57	w	119	77
CAN	24	18	8	56	38	X	88	58	х	120	78
EM	25	19	9	57	39	Υ	89	59	у	121	79
SUB	26	1A	:	58	3A	Z	90	5A	z	122	7A
ESC	27	1B	;	59	3B]	91	5B	{	123	7B
FS	28	1C	<	60	3C	\	92	5C		124	7C
GS	29	1D	=	61	3D]	93	5D	}	125	7D
RS	30	1E	>	62	3E	\wedge	94	5E	~	126	7E
US	31	1F	?	63	3F	_	95	5F	DEL	127	7F

- 7.7 Edit text operation and delete operation
- ◆There are two methods to edit the text, one is by direct input according to the table, the other is by PC
- ◆Indicator could save 20 characters for company name(16 characters for built in printer); 10 characters for goods name, customer name
- -Method 1, by direct input
- ▲Each character corresponds one decimal numeric,
- ▲4 bits 0000 means edit finish
- ▲Save only when edit finish, press [weigh] while edit, then edit won't be saved
- ▲While edit, the highest 2 bits(left) indicates the character number one has edited(one character takes up 0.5 size)
- ◆Example: Operation for edit goods no. and name

Step	Operation	Display	Note
1	Press	[PSt 00]	Indication to input
	[parameter]		parameter type
2	Press[10]	[PSt 10]	To edit goods name,
	Press[INPUT]		press [10]
3		[Hn ***]	Indication to input
			goods no.
4	Press[001]	[Hn 001]	To input goods no.

Step	Operation	Display	Note
	Press[INPUT]		
5		[0 ****]	Indication to input
			the first letter of
			the goods name
6	Press[0034]	[0 0034]	To input code of "A"
	Press[INPUT]		
7		[0.5 ****]	Indication to input
			the second letter of
			the goods name [Note]
8	Press[0081]	[0.5 0081]	To input code of "p"
	Press[INPUT]		
9		[1.0 ****]	Indication to input
			the third letter of
			the goods name
10	Press[0081]	[1.0 0081]	To input code of "p"
	Press[INPUT]		
11		[1.5 ****]	Indication to input
			the forth letter of
			the goods name
12	Press[0077]	[1.5 0077]	To input code of "l"
	Press[INPUT]		
13		[2.0****]	Indication to input
			the fifth letter of
			the goods name

Step	Operation	Display	Note
14	Press[0]	[2.0 0000]	To input "0" to
	Press[INPUT]		finish edit the goods
			name
15	Press[WEIGH]	[Hn 002]	Indication to input
			the next goods no.
16		[*****	Return to weighing
			status

Method 2, by PC

- ◆There are 6 commands that can be executed by PC, two are for control, the other 4 are for transfer from no. to text info.

 All commands begin with ② and end with ;
- -Control command
- @S; (Begin exection command, when indicator receive this command, then it begins to execute the following command)
 @E; (Finish exection command, when indicator receive this command, then it finishes executing)
- -Transfer command
- 1,To transfer goods no to goods name @A***:'\$\$\$\$\$';
- *** is the goods no.(000~200), it must be a 3-bits no.'\$\$\$\$' is the goods name, goods name in English must with set of ''

```
2,@B***:'$$$$;';
*** is the customer no.(000~099), it must be a 3-bits no.'$$$$'
is the customer name, customer name in English must with set
of \'
3,@C***:'$$$$;';
*** is the note no.(000~099), it must be a 3-bits no.'$$$$' is
the note text, note text in English must with set of ''
4,@D:'$$$$;;
'$$$$' is the company name
◆Example: one programe
@S;
@A001:'apple';
@B001:'Coco cola';
@C001:'Drink field';
@D:'Shanghai Yaohua';
Save the file as .txt format,
```

@Ε;

1,Prepare the txt. File first;

2,Connect the indicator to PC;

3,Open serial port communication software(Hyper terminal is WINDOWS OS) and configure the parameter such as baud rate;

4,Press [parameter], indicator displays [PSt 00], input 30, then press [input], indicator display [L 00000], input download password "31901", then press [input], indicator display [ld ----] to download

5,Open the .txt file, indicator display [ld***] (*** indicates the string indicator has downloaded)

6,When download finished, indicator display [End], then indicator returns back to weighing status.

7.8 Delete operation for the text info

Then operate as followed steps:

Step	Operate	Display	Note
1		[PSt 00]	Input parameter type
	PRESS[Parameter]	[PSt 40]	no.
	PRESS[40]		40:Delete all goods
	PRESS[INPUT]		name;
			41:Delete all
			customer name
			42:Delete all note
			text
			43:Delete company
			name
			49:Delete all info
2		[C 000000]	If encrypt is
	PRESS[888888]	[C 888888]	required
	PRESS[INPUT]		
3		[SurE 0]	0-not delete
	PRESS[1]	[SurE 1]	1-delete
	PRESS[INPUT]		
4			Delete finish

8.CODE DISPLAY

8.1 Normal information

-....

Wait a moment, and this is a normal display;

- Prnt

Wait a moment, data transmitted between indicator and printer

- LoAd

Fist time save in two times weighing mode

-SAUE:

No choice for printer of printer type is 0

-EnD

Operation finish

-PASS

Password change success

8.2 Error code display

- Err 03

Overload warning

- Err 08

No weighing records under this requirement

- Err 09

Not exit this truck no.

- Err 10

Truck no. number more than 1500

- Err 12

Can't print with built in printer

- Err 13

Wrong selection for parameter type	Problem at A/D conversion	
-Err 14		
Without limit of the character number you can input	8.4 Code for components error	
-Err 15	-Err 18	
Wrong selection for parameter no.	Key board has problems	
-Err 16	-Err 21	
Wrong input for password	Calibration data lost	
-Err 17	-Err 22	
Parameter set not meet requirement	Real clock damaged	
-Err 19	-Err 23	
Can't print due to 0 or negative value	E^2 PROM has been damaged	
-Err 28	-	
Date for print is less than saved date in indicator	-Err 21	
	Calibration data lost	
8.3 Code for wrong set up	8.5 Code for others	
- Err P	-Err 25	
Wrong connection for printer or problem at printer	Illegal software, or ${ t E}^2{ t PROM}$ was damaged	
Flores 0.1	- ctnu 0	
- Err 01	Indicator will display this if it can not receive the stable	
Load cell problem or load cell connection problem	data within 25 seconds during step 8 or step 9 of the calibration	
- Err 05	process. At this time, the operator can input 0, 1 or 2:	

0: (Abort) The indicator will not do this step and INPUT next step

1: (Retry) Try again

2: (Ignore) The unstable data can be used

-ISP

Indicator is at ISP satus

APPENDIX

Appendix 1:Calibration rate

E:001

dc:3

Pn:10123

Flt:1

F:5.000

A:22081

L:681589

LH:54.08

b:270394

o:681589

oH:54.08

c:999999

t:794484

Appendix 2:Print format

-Linked format(3 page, upright)

COCO COMPANY COCO COMPANY
WEIGHING BILL WEIGHING BILL

NO.	001
Date	1999-07-28
Time	12.02.31
Tr no	12345
Ca no	022
Gross	2.000(kg)
Tare	0.3000(kg)
Net	1.7000(kg)
Cutom	FAS.CO
NOTE	CHARK

NO.	001		
Date	1999-07-28		
Time	12.02.31		
Tr no	12345		
Ca no	022		
Gross	2.000(kg)		
Tare	0.3000(kg)		
Net	1.7000(kg)		
Cutom	FAS.CO		
NOTE	CHARK		

	NO.	001
	Date	1999-07-28
	Time	12.02.31
	Tr no	12345
	Ca no	022
	Gross	2.000(kg)
	Tare	0.3000(kg)
	Net	1.7000(kg)
	Cutom	FAS.CO
	NOTE	CHARK
	NOTE	CHARK

-Linked format(1 page,across)

COCO COMPANY

WEIGHING BILL DATE: 2004-03-05

NO.	Time	T no.	Cg no.	GW(kg)	TW(kg)	NW(kg)	Cust	NOTE
0001	12.02.24	12222	022	2.000	0.300	1.700	FAS CO.	CHARK

-Record format

COCO COMPANY

Weighing bill Date: 2004-03-05

NO.	Time	T no.	Cg no.	GW(kg)	TW(kg)	NW(kg)	Cust	NOTE
0001	12.02.24	12222	022	2.000	0.300	1.700	FAS CO.	CHARK
0002	12.03.24	12223	023	2.000	0.300	1.700	FAS CO.	CHARK

Accum Gross W: 4.000(kg) Net W: 3.400(kg)

-Filled-in format

WEIGHT BILL				
Fist bi	ll for ope	rator		
SERIAL No.	123			
DATE	1999-07-28	3		
TIME	12.35.28			
VEHICLE No.				
GOODS No.				
GROSS	1580	kg		
TARE	80	kg		
DISCOUNT	10	olo		
NET	1350	kg		
CUSTOMER	FAS CO.			
NOTE	CHARK			

-General Report

General Report

	1						
NO.	Date	Time	Truck	Cago	Gro W(kg)	Ta W(kg)	Net W(kg)
0001	1999-05-28	12.02.24	12222	022	2.000	0.300	1.700
0002	1999-06-28	12.03.24	12345	033	2.000	0.300	1.700
0003	1999-07-28	12.03.24	00888	033	2.000	0.300	1.700
0004	1999-08-28	12.04.11	00888	022	2.000	0.300	1.700
А	Accum: To send Gross W: To send8.000(kg) Net W: To send7.800(kg)						

-Report by time

Report 1 (by time) Date:1999-07-28

NO.	Time	Truck no.	Cago no.	Gro W(kg)	Ta W(kg)	Net W(kg)	
0001	12.02.24	12222	022	2.000	0.300	1.700	
0002	12.03.24	12345	033	2.000	0.300	1.700	
0003	12.03.24	00888	033	2.000	0.300	1.700	
0004 12.04.11 00888 022 2.000 0.300 1.700							
Accum	Accum Gross W: 8.000(kg) Net W: 6.800(kg)						

-Report by truck no.

Report 2 (by truck no.)

Ľ	ate:	199	9-07-28

NO.	Truck no.	Ta W(kg)	Time	Gro W(kg)	Net W(kg)
0001	12222	0.300	0002	4.000	3.400
0002	12345	0.300	0002	4.000	3.400
0003	00888	0.300	0002	4.000	3.400

-Report by goods no

Report 3 Date: 1999-07-28

NO.	Goods no.	Time	Net W(kg)
0002	022	0002	3.400
0003	033	0002	3.400

Appendix 3: Example for edit

1, Edit the goods name according to a goods no.(Now to define goods no. "001" as "Apple" $\,$

Step	Operation	Display	Note
1	Press [parameter]	[PSt 00]	Indication to input parameter
			type
2	Press[10]	[PSt 10]	To edit goods name, press [10]
	Press[INPUT]		
3		[Hn ***]	Indication to input goods
			no.
4	Press[001]	[Hn 001]	To input goods no.
	Press[INPUT]		
5		[0 ****]	Indication to input the first
			letter of the goods name
6	Press[0034]	[0 0034]	To input code of "A"
	Press[INPUT]		
7		[0.5 ****]	Indication to input the
			second letter of the goods
			name[Note]
8	Press[0081]	[0.5 0081]	To input code of "p"

Step	Operation	Display	Note
	Press[INPUT]		
9		[1.0 ****]	Indication to input the third
			letter of the goods name
10	Press[0081]	[1.0 0081]	To input code of "p"
	Press[INPUT]		
11		[1.5 ****]	Indication to input the forth
			letter of the goods name
12	Press[0077]	[1.5 0077]	To input code of "l"
	Press[INPUT]		
13		[2.0****]	Indication to input the fifth
			letter of the goods name
14	Press[0]	[2.0 0000]	To input "0" to finish edit
	Press[INPUT]		the goods name
15	Press[WEIGH]	[Hn 002]	Indication to input the next
			goods no.
16		[*****	Return to weighing status

2, Edit the customer name according to a customer no. (Now to define customer no. "001" as "Shanghai Yaohua"

Step	Operation	Display	Note	
1	Press[parameter]	[PSt 00]	Indication to input	
			parameter type	
2	Press[11]	[PSt 11]	To edit customer name, press	

	Press[INPUT]		[11]
3		[cn **]	Indication to input customer
			name
4	Press[001]	[Cn 001]	To input customer no.
	Press[INPUT]		
5		[0 ****]	Indication to input the
			first letter of the customer
			name
6	Press[0052]	[0 0052]	To input code of "S"
	Press[INPUT]		
7		[0.5 ****]	Indication to input the
			second letter of the
			customer name
8	Press[0073]	[0.5 0073]	To input code of "h"
	Press[INPUT]		
9		[1.0 ****]	Indication to input the
			third letter of the customer
			name
	Press[0000]	[7.5 0000]	To input "0" to finish edit
	Press[INPUT]		the customer name
	Press[WEIGH]	[cn 02]	Indication to input the next
			customer no.
		[*****]	Return to weighing status

3, Edit the text info according to a text no.(Now to define text no. "001" as "John" $\,$

Step	Operation	Display	Note
1	Press[parameter]	[PSt 00]	Indication to input
			parameter type
2	Press[12]	[PSt 12]	To edit text info, press [12]
	Press[INPUT]		
3		[bn **]	Indication to input text no.
4	Press[01]	[bn 01]	To input text info
	Press[INPUT]		
5		[0 ****]	Indication to input the
			first letter of the text info
6	Press[0043]	[0 0043]	To input code of "J"
	Press[INPUT]		
7		[0.5 ****]	Indication to input the
			second letter of the text
			info.
8	Press[0070]	[0.5 0070]	To input code of "o"
	Press[INPUT]		
9		[1.0 ****]	Indication to input the
			third letter of the text
			info.
	Press[0000]	[2.0 0000]	To input "0" to finish edit
	Press[INPUT]		the text info.

Press[WEIGH]	[bn 02]	Indication to input the next
		text no.
	[*****	Return to weighing status

4, Edit the printed customer name(Now to edit "GE GROUP")

Step	Operation	Display	Note
1	Press[parameter]	[PSt 00]	Indication to input
			parameter type
2	Press[13]	[PSt 13]	To edit printed customer name
	Press[INPUT]		
3	Press [INPUT]	[dn]	Indication to input printed
			customer name
4		[0 ****]	Indication to input the first
			letter of the printed
			customer name
5	Press[0040]	[0 0040]	To input code of "G"
	Press[INPUT]		
6		[0.5 ****]	Indication to input the
			second letter of the text
			info.
8	Press[0038]	[0.5 0038]	To input code of "E"
	Press[INPUT]		
9		[1.0 ****]	Indication to input the third
			letter of the printed

		customer name
		:
Press[0000]	[4.0 0000]	To input "0" to finish edit
Press[INPUT]		the printed customer name
Press[WEIGH]	[*****]	Return to weighing status

Appendix 4: Example for print

One-time weighing, manually pre-tare weighing bill print

Step	Situation	Operation	Display	Note
1	Truck pass	Press[TARE	[P00.000]	Indication to input tare
	the scale	parameter]		value
2		Press[1000]	[P01.000]	To input the tare value
		Press[INPUT]		
3			[-1.000]	Display the gross/net
				weight, tare light is
				on(Press[gross/net] key
				to switch the display)
4	Wait until	Press[Save1]	[0 *****]	Indication to input new
	stable	or		truck no.
		Press[Save2]		
5	Input	Press [00123]	[0 00123]	
	truck no.	Press [INPUT]		
6			[Hn ***]	Indication to input new
				cargo no

7	Input	Press[011]	[Hn 011]	
	cargo no.	Press[INPUT]		
8			[cn **]	Indication to input new
				customer no.
9	Input	Press[11]	[cn 11]	
	customer	Press[INPUT]		
	no.			
10			[bn **]	Indication to input new
				text info no.
11	Input text		[bn 05]	
	info no.			
12			[Prnt]	To print out the weighing
				bill